M.A.C. SOLUTIONS

PROCESSVUE

Creating the Web Connector Views in the Archiver Configurator

Abstract

Using the Data Archiver Configurator to create Web Connector Views to be visible in SOE/Analyser. This will allow you to configure Areas and assign Connectors to those Areas.

To setup the Web Connector Views in the Archiver Configurator first:

1. Go to the Analyser Web App and login with the pvadmin account



2. Go to – User > Admin Manager



3. Select the Roles tab



4. Create the required Roles and check/uncheck the different Role Policies to your requirement



5. Select the Users tab and assign a Role to a User



For a User who has a NEW Role assigned to them, the Web Connector Views need to be setup in the Archiver Configurator for this to happen. To achieve this:

1. Open the ProcessVue Archiver Configurator



2. To login, click on the IP Address and enter the Username and Password
   a. Username: Admin
   b. Password: admin



3. Once logged in, scroll down to Web Conn Views in the left-hand pane



4. By Default, the 'Users' will be selected which is what will be used for the pvadmin and Administrator accounts.



5. Use the Dropdown list to switch to your new Role



6. To copy a configuration from another Role, select the Copy button and pick which Role to copy the configuration from. For example, to copy the Users Role to Engineer, select the Engineer Role, click the Copy button, and select Users



7. Click OK to confirm the Selection then click Save for the settings to be saved.

Once these steps have been completed and you have signed in to the ProcessVue Web Application with your new User with their assigned Role, you will be able to see the same views/connectors/data as the pvadmin account without the administrative rights.